ARXS50G



Notes
1. Refer to purchasing specification AS303002, unless otherwise specified.
2. This drawing was drawn on CAD system.
3. The electric wiring diagram label is 3P193830-1.

Z1C–Z5C	: Ferrite core
X1M,X2M	: Terminal strip
Y1E	: Electronic expansion valve coil
V2,V3,V5,V6,V11	: Varistor
SA2	: Surge arrester
FU1,FU2,FU3	: Fuse
AC1,AC2	
U,V,W,X11A,	
X12A,E1,E2	
HR1,HR2	: Connector
MRM10, MRM20,	
MRC/W	: Magnetic relay

R1T–R3T	: Thermistor
S2–S102	: Connector
LEDA	: Pilot lamp
L	: Live
N	: Neutral
SW1	: Forced operation on/off SW (SW1)
SW4	: Local setting SW (SW4)

M1C	: Compressor motor
M1F	: Fan motor
L1R	: Reactor
Q1L	: Overload protector
PM1	: Power module
PCB1, 2	: Printed circuit board
Y1R	: Reversing solenoid valve coil
Sheet metal	: Terminal strip fixed plate