

Field wire

Symbol explication

- I = Pair
- II = Twin
- III = Triple
- M = Master
- S = Slave
- 1 = Earth leak detector
- 2 = Fuse
- 3 = Remote control

