


# RXS50J



## Notes

1. Refer to purchasing specification AS303002, unless otherwise specified.
2. This drawing was drawn on CAD system.
3. The electric wiring diagram label is 3P193830-1.

Z1C-Z5C : Ferrite core  
 X1M,X2M : Terminal strip  
 Y1E : Electronic expansion valve coil  
 V2,V3,V5,V6,V11 : Varistor  
 SA2 : Surge arrester  
 FU1,FU2,FU3 : Fuse  
 AC1,AC2 : Connector  
 U,V,W,X11A, X12A,E1,E2 : Connector  
 HR1,HR2 : Connector  
 MRM10, MRM20, MRC/W : Magnetic relay

R1T-R3T : Thermistor  
 S2-S102 : Connector  
 LEDA : Pilot lamp  
 L : Live  
 N : Neutral  
 SW1 : Forced operation on/off SW (SW1)  
 SW4 : Local setting SW (SW4)

M1C : Compressor motor  
 M1F : Fan motor  
 L1R : Reactor  
 Q1L : Overload protector  
 PM1 : Power module  
 PCB1, 2 : Printed circuit board  
 Y1R : Reversing solenoid valve coil  
 Sheet metal : Terminal strip fixed plate