



Key:

- - Field supply wiring
- AS - Air swing motor
- DP - Drain pump
- Z1C - Ferrite core
- Heat - With jumper for heat pump
- Without jumper for cooling
- Valve - With jumper for valve application
- Without jumper for valveless application

