



BAE20A

WIRING DIAGRAM

BS1	PUSH BUTTON (FIELD TRIAL OPERATION)	S1C	LIMIT SWITCH (CYLINDER START)	
BS2	PUSH BUTTON (NO FUNCTION)	S2C	LIMIT SWITCH (CYLINDER END)	
DS1	1	DIP SWITCH (ON:FILTER CLEANING PROHIBITION MODE)	S3C	LIMIT SWITCH (BRUSH START)
	2	DIP SWITCH	S4C	LIMIT SWITCH (BRUSH END)
		M1	MOTOR (CYLINDER)	
		M2	MOTOR (BRUSH)	

- NOTES: 1. ,  THESE SYMBOLS SHOWS CONNECTORS.
 2. WHEN DS1-1 IS TURNED ON, IT WILL BE SET TO FILTER CLEANING PROHIBITION MODE.
 3. POWER SUPPLY TO THE ADAPTER WILL BE CONNECTED TO THE CONNECTORS (X1A AND X13A) OF A1P.

