



**Key:**

- - Field supply wiring
- AS - Air swing motor
- DP - Drain pump
- Z1C - Ferrite core
- [Heat] - With jumper for heat pump  
- Without jumper for cooling
- [Valve] - With jumper for valve application  
- Without jumper for valveless application

