






UATYA40-50BBAY1



Air direction	Discharge	Intake
Left	LD	/
Rear	/	RI
Front	FD	/

Sci	Signal cables inlet	Esi	Electrical supply inlet
Cd	Condensate drain 1" male	Rfi	Remove for inspection
			Clearances