
AZQS100-140B8V1



- 1 The pipes between the branch and the indoor units should have the same size as the indoor connections.
- 2 The check valve is only present in following models: AZQS100 and AZQS125.

Filter