


## Max fresh air intake volume table

The rise of operating sound with fresh air intake kit



The maximum intake air flow volume is following table.

If the intake air flow volume is too large, the operating sound may rise or detection of the indoor unit suction temperature may be affected.

| FCQG-F                                            | 35  | 50  | 60  | 71  | 100 | 125 | 140 |
|---------------------------------------------------|-----|-----|-----|-----|-----|-----|-----|
| Max fresh air intake volume (m <sup>3</sup> /min) | 2.5 | 2.5 | 2.7 | 3.0 | 4.5 | 5.2 | 5.2 |