


RZQG100-140L(8)Y1



- Notes:
- 1 The pipes between the branch and the indoor units should have the same size as the indoor connections.
 - 2 The check valve is only present in following models: RZQSG100 and RZQSG125.