


RZQSG125-140L(8)Y1



Notes:

- 1 The pipes between the branch and the indoor units should have the same size as the indoor connections.
- 2 The check valve is only present in following model: RZQSG125.