


Technical drawing of a window frame assembly. The drawing shows a cross-section of the frame with various dimensions and components labeled. Key dimensions include 300 o menos (300 or less), 420, 710 (po), 860 - 910 (tech), 420, 55, 35, and 0. Components are labeled with numbers 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100. A note at the bottom reads: (Consulte la nota 3).



	Modelo	
256	FCQG100-140FVEB, FXFQ80-100AVEB	
298	FCQHG71-140FVEB, FXFQ125AVEB	3D077130