

## Notes

1. The pipes between the branch and the indoor units should have the same size as the indoor connections.