


ARXC50-71D
RXC50-71D



NOTATION

- MC : Compressor motor
- MF : Fan motor
- OLP : Overload protector
- TB : Terminal block
- EXV : Electronic expansion valve coil
- X11A, X12A : Connector
- Z1C, Z2C, Z3C : Ferrite core
- 4WV : Four way valve
- — — : Field supply wiring