

CONNECTOR	FG, HE, S6~S900
FUSE	F1U (FU1)
TRANSFORMER	T1R (L301)
FAN MOTOR	M1F
SWING MOTOR	M1S
MAGNETIC RELAY	K1R (MR10)
PRINTED CIRCUIT BOARD	A1P~A4P
THERMISTOR	R1T, R2T
OPERATION SWITCH	BS1 (S1W)
VARISTOR	R2V (V2)
TERMINAL STRIP	X1M
FERRITE CORE	Z1C, Z2C
INTELLIGENT POWER	IPM200
MODULE	H1P, H2P (LED 1~2)
PILOT LAMP	
PROTECTIVE EARTH	
DIODE BRIDGE	V1R (DB301)
BUZZER	H10 (BZ)
CAPACITOR	C101~302
SIGNAL RECEIVER	SR (WLU)

WIRE COLORS


BLK	:BLACK	GRN	:GREEN
RED	:RED	YLW	:YELLOW
BLU	:BLUE	ORG	:ORANGE
WHT	:WHITE		

FIELD WIRING



CAUTION:
WHEN THE MAIN POWER IS TURNED OFF AND THEN BACK ON AGAIN, OPERATION WILL RESUME AUTOMATICALLY.

WIRING DIAGRAM



NOTES:

1. SIZE: HEIGHT 70 X WIDTH 120.
2. REFER TO PURCHASING SPECIFICATION AS303002 UNLESS OTHERWISE SPECIFIED.